



Head Office, SHGB Bhawan, Plot no. 1, Sector-3, Rohtak
General Administration Division

Sealed tenders are invited for renovation of our building at Sector -44 Gurgaon wherein vitrified tiles flooring & granite work etc. is to be done. The interested contractors may submit their bid to Regional Manager, Sarva Haryana Gramin Bank, Plot no. 36 (p), institutional area, Sector 44, Gurgaon. The last date of submission of bids is 15/04/2017. The details are given in our web-site www.shgb.co.in.

General Manager

Terms & Conditions for renovation of building of

Sarva Haryana Gramin Bank, Plot no. 36 (p), institutional area, Sector 44, Gurgaon

- 1 Contractor must have good reputation & work experience to construct big buildings.
- 2 The contractors will visit our site at Sarva Haryana Gramin Bank, Plot no. 36 (p), Institutional Area, Sector 44, Gurgaon & contact Regional Manager and after discussion with regard to work to be done, submit their bid in enclosed performa.
- 3 The vendor has to complete the said work with in 30 days from the date of order.
- 4 The payment will be made within 7 days on completion of work & submission of bills.
- 5 All bids are to submitted to Regional Manager, Sarva Haryana Gramin Bank, Plot no. 36 (p), institutional area, Sector 44, Gurgaon. (Mobile No. 8800297634)
- 6 The registered contractors having license in the field will be preferred.
- 7 All bids are to be furnished in sealed cover and envelope must contain mobile & full address of the contractor.

Chief Manager

General Manager

PRICE BID FOR RENOVATION OF SARVA HARYANA GRAMIN BANK BUILDING AT PLOT NO.36P,SECTOR 44
INSTITUTIONAL AREA,GURGAON

SN	ITEMS/ELEMENT	SPECIFICATION	Area (Sq Ft)	Rate per Sq ft	Amount
1	Vitrified tiles flooring	Providing & repairing of Ex. Flooring with vitrified tiles(colour should be ivory shade/matchable) joint free of minimum 9 mm thickness,size 24"X24", 4"skirting,allfixed in neeru mortar,complete with cutting and filling joints with white cement. Make of tiles Johnson/Bell/Euro/Asian/Nitco/Naveen/Somani. Shade as per bank specified			
2	Granite slabs	P/F of 19 mm thick granite slabs(to match with existing color and pattern) after descaling the damaged portions/partially(wall cladding) to be fixed/ repaired by means of clamps inside the wall @ suitable gaps and 1:3 S.Sand Mortar making it completely.			
3	Other work if any	Detail of work to be specified			
		Total cost			

Signature of the contractor